FIG. 1


RAW MATERIAL (CONTAINING ZINC)
REFINEMENT (SOLVENT EXTRACTION, ACTIVATED CARBON TREATMENT)
ZINC OXIDE
(HOT PRESSING)
(TARGET)
(SPUTTERING)
(THIN FILM)